Field Visit Safety Audit

General Information

Announced Unannounced	Test Person	Storm Restoration
	Auditor	Job Activity
2024-06-05	29 Maureen Ave, Randolph, ME 04346	Different Person
Date	Location	Supervisor
Time: 19:46:00		
Time		

Crew

Employees

Additional Crew

Item	Yes	No	N/A	Notes
Proper Vehicle Placement	₩			
Wheel Chocks in Use	₽			
Outriggers in Use	₽			
Warning Lights in Use	₩			
Traffic Signs Used and Proper Placement	₽			
Traffic Cones	₩			
Bucket Liner	₩			
Cleaning & Testing Log Book	₩			
Vehicle Inspection Book (Up-To-Date)	₩			
Backup Alarms	₽			
	•		•	
Personal Protective Equipment Item	Yes	No	N/A	Notes
Hard Hat	res 	NO	IN/A	Notes
Safety Glasses		ႜ	╫	
Face Shield		ႜ	╁┼	
Fire Retardant Clothing		ႜ	╁┼	
Safety Toe Boots		ႜ	╁┼	
Leather Work Gloves		╁┼	╁	
Traffic Vest		ᆂ	╁	
Rubber Gloves		十一	一	
Rubber Sleeves		一	一	
Fall Protection(Use & Inspection)		一	一	
Hearing Protectors		一	一	
Hand Line / Safety Line		一	一	
Air Monitoring / Sniffer		一	一	
Slings Inspected (Condition Acceptable Y/N)			一	
Nork Area Item	Yes	No	N/A	Notes
Flagman	res ✓	INO	IN/A	Notes
Stop/Slow Signs		ႜ	╫	
Keep Pedestrians Out of Harms Way		ᆂ	╫	
Communication Available		╁╬╴	╫	
Work Area Guards / Barriers		ᆂ	╫	
		╂	╫	
Atmospheric Test Equipment		 		
Material/Equipment Storage		 	 	
Area Policed After Job Completed		뉴	뉴	
"Safe Zone" Established				

Safety Equipment

Item	Yes	No	N/A	Notes
First Aid Kit (Up To Date)	~			
Fire Extinguisher (Monthly Inspection)	₽			
Rubber Hoses/Rubber Blankets				
Pole Guards	⊘			
Ground Truck/Barricade	₽			
Switching & Tagging	₽			
Confined Space Rescue Equipment	₽			

The Job

Item	Yes	No	N/A	Notes
Pre-Job Briefing (Send Weekly)	⊘			
Stretching Exercise (Daily)	⊘			
Weekly Safety Mtgs. (Send Weekly)				

Comments

Testing new submissions

GPS Location

<u>Map</u>

Images